

## CASE HISTORY SPOTLIGHT

## Case History #596: Stone Cladding Tile Repair with MCI®



A residential building less than 10 years old began to have trouble with stone cladding tiles falling off the exterior. The culprit was corrosion on concrete reinforcement and stone cladding anchors.

ISO/IEC-17025

To repair the structure, unstable cladding tiles were removed. Holes were drilled into grout lines to inject MCI<sup>®</sup>-2020 Gel beneath the surface. MCI<sup>®</sup>-2006 NS was also injected into voids behind the cladding tiles. Drill holes were sealed, grout lines renewed, and tiles were re-anchored and replaced where necessary.

The project was considered a success. A visual survey three years later found no sign of further corrosion damage. The project was even featured in a presentation on restoring stone structures given by the specifying engineer at an engineering convention about five years after the repair.

Read the full case history here: https://www.corteccasehistories.com/?s2member\_file\_ download=access-s2member-level1/ch596.pdf

4119 White Bear Parkway, St. Paul MN 55110 USA Phone (651)429-1100, Toll free (800) 4-CORTEC Fax (651) 429-1122, Email: info@cortecvci.com www.cortecvci.com



Printed on recycled paper/100% Post Consumer

©2019, Cortec<sup>®</sup> Corporation. All Rights Reserved. Copying and/or manipulation of these materials in any form without the written authorization of Cortec<sup>®</sup> Corporation is strictly prohibited. ISO Accreditations apply to Cortec's processes only.