



CASE HISTORY

VpCI®-416 & VpCI®-426 Used For Reservoir Restoration



DATE
July 2008

CORTEC® REPRESENTATIVE
CorteCros Ltd.

CUSTOMER
Pecon

LOCATION
Zagreb, Croatia

PRODUCTS
VpCI®-416
VpCI®-426

PROBLEM
The aluminum plated reservoir surface was damaged from dirt, grease, and corrosion. Pecon required the reservoir to be clean and corrosion free before shipping.

APPLICATION
VpCI®-426 was diluted with water 25-30% and a mechanical brush was used to remove the dirt, grease, and corrosion. After cleaning, the reservoir was rinsed with VpCI®-416, which was diluted with water 25%. The surface was air dried and then loaded for shipment.

CONCLUSION
The customer was very satisfied with the Cortec® products, not only solving their corrosion problem, but accomplishing it easily and economically.



4119 White Bear Parkway, St. Paul MN 55110 USA
Phone (651)429-1100, Toll free (800) 4-CORTEC
Fax (651) 429-1122, Email: info@cortecvci.com
www.cortecvci.com

ch356 5/2010

Printed on recycled paper 100% Post Consumer

©2009, Cortec Corporation. All Rights Reserved. Copying of these materials in any form without the written authorization of Cortec Corporation is strictly prohibited.

