

# CASE HISTORY

## Valve Bonnet Spares Preservation

### CORTEC® REPRESENTATIVE

Cortec® Corrosion Solutions India Pvt Ltd

### DISTRIBUTOR

Vertex Corrotech Solutions Pvt Ltd

### LOCATION

Coimbatore, South India

### PRODUCTS

VpCI®-422

VpCI®-419

### PROBLEM

GE wanted to use valve bonnet spares that had been stored for more than five years and were in a rusted condition. GE's policy did not permit phosphating or any other harmful chemical process, so an environmentally friendly rust removal product was needed.

### APPLICATION

Cortec® VpCI®-422, an organic and biodegradable rust remover, was applied to the valve bonnets and neutralized with VpCI®-419 cleaner/degreaser. It only took 45 minutes to remove the rust, and the bonnets were soon restored to a ready to use condition.



### DATE

July 2014

### CUSTOMER

GE Energy

## CONCLUSION

GE Energy was extremely pleased with the performance of Cortec's innovative products, as well as the service support and cost effectiveness.

