



CASE HISTORY

Parts Preservation



DISTRIBUTOR

Multiweld Engineering Pvt. Ltd.

LOCATION

Gurgaon, India

PRODUCTS

VpCI®-377

PROBLEM

The customer faced a corrosion issue on their final product after using Castrol DW 902. The customer wanted rust prevention solution that would last 8-10 months and be compatible with rubber components.

APPLICATION

VpCI®-377, a water-based rust preventive diluted 1:1 with demineralized water, was applied to the components.

CONCLUSION

The customer was satisfied with Cortec's eco-friendly and user friendly rust preventive and its compatibility with rubber. The customer also appreciated the product's good surface finish which became dry over time.

DATE

April 2013

CUSTOMER

Anand Motors

CORTEC® REPRESENTATIVE

Cortec® Corrosion Solutions India Pvt Ltd



CORTEC
CORPORATION

Environmentally Safe VpCI®/MCI® Technologies

www.cortecvci.com