

CASE HISTORY

Restoration of Pump Housings for Export



DATE

June 2012

CUSTOMER

VR Foundries

CORTEC® REPRESENTATIVE

Cortec® Corrosion Solutions India Pvt Ltd

DISTRIBUTOR

Vertex Corrotech Solutions Pvt Ltd

LOCATION

Coimbatore, India

PRODUCTS

VpCI®-426

VpCI®-419

VpCI®-369 N5

PROBLEM

Approximately 100 pump housings were sent to the customer from a subcontractor. No rust preventive had been applied, so the parts had developed rust. The customer needed to export the parts immediately and approached Cortec® for removal of the rust.

APPLICATION

VpCI®-426 rust remover was applied to the pump housings by brush. The parts were then cleaned and neutralized with VpCI®-419. Finally, VpCI®-369 N5 was applied to the cleaned parts to prevent future rust.



CORTEC
CORPORATION

Environmentally Safe VpCI®/MCI® Technologies

www.cortecvci.com

CONCLUSION

The task was completed within 48 hours, further strengthening the customer's confidence in the performance of Cortec® products and the capabilities of Vertex Corrotech Solutions to provide a solution for implementing "Total Corrosion Control."

