

ENVIRONMENTAL

SYSTEM REGISTERED




<ul> <li>Phone: (651)</li> <li>Toll Free: (80)</li> </ul>	Bear Parkway, St. Pa ) 429-1100, Fax: (6: 00) 4-CORTEC, E-ma • corteclaboratorie	ul, MN 55110 USA 51) 429-1122 ill: info@cortecvci.com ss.com	
	Eval	uating Rust Preventives on Tube Sections	
From:	<ul> <li>Cortec Corporation Laboratories</li> <li>4119 White Bear Parkway</li> <li>St.Paul, MN 55110</li> </ul>		
cc: Boris Miksic Anna Vignetti Jessica Scott Cliff Cracauer Bob Boyle			
Project	#: 11-00	8-1825(bis)	
Test co	nducted by:	Ein Untala	
•		Eric Uutala Technical Service Engineer	
Approved by:		U. Khaishan Margarita Kharshan Laboratory Director	
Date:		March 22, 2011	
0 0 0			

Background:	Customer sent 3 pipe sections to Cortec for evaluation. They would like their current rust preventive liquid to be tested and compared to similar Cortec products.
Sample Received:	Three pipe sections, ~6" I.D.
Method:	ASTM D-1735 Water Fog (100°F, ~95% relative humidity)
Materials:	Three pipe sections Rustilo 4135 HF EcoLine 3690 BioCorr
Procedure:	<ol> <li>The following procedure was used:</li> <li>Upon receipt, all three pipe sections were cleaned thoroughly with methanol.</li> <li>After cleaning, pipe sections were dipped in one of the following:         <ul> <li>a. Rustilo 4135HF (used as received)</li> <li>b. BioCorr Rust Preventative</li> <li>c. EcoLine 3690</li> </ul> </li> <li>After dipping, pipes were allowed to drip dry overnight.</li> <li>All pipes were then placed in ASTM D-1735 water fog cabinet.</li> <li>After 696 hours, all pipes were removed from ASTM D-1735 water fog cabinet.</li> <li>After fog cabinet.</li> <li>All pipes were visually inspected and photographed.</li> </ol>
<b>Results:</b>	The following results were found:

Pipe Treatment	Time to Corrosion (Hours)
Rustilo 4135 HF	96
BioCorr	264
EcoLine 3690	DNF

DNF – Did not fail during 696 hours of ASTM D-1735 testing.

## **Photos:**





## **Interpretations:**

EcoLine 3690 provided the best protection in this test, with no corrosion present after 696 hours of testing. On the other two pipes, corrosion was focused on the edges of the pipe, with small amounts of corrosion forming on the body of the pipe as testing went on.

In addition to providing superior corrosion protection, both Cortec products are made from renewable resources, soybean oil (BioCorr) and canola oil (EcoLine 3690).