


## **CASE HISTORY SPOTLIGHT**

## Case History #21: Solving Restaurant Grease Trap and Sewer Problems



Frequent sewer clogging—plus bad smells from the grease trap—had become a headache at one restaurant in Russia. In 2017, they decided to try adding Bionetix<sup>®</sup> ECO-TRAP<sup>TM</sup> L and BCP22<sup>™</sup> to the sewer pipe and grease trap. The results were so good that the restaurant wrote an official letter recommending the products for use in other food production facilities!

Read the full case history here: <u>https://</u> <u>www.bionetix-international.com/</u> <u>wp-content/uploads/Restricted\_Case\_</u> <u>Histories/ch021.pdf</u>

©2021, Bionetix<sup>®</sup> International. All Rights Reserved. Copying and or manipulation of these materials in any form without the written authorization of Bionetix<sup>®</sup> International is strictly prohibited. ISO Accreditation applies to Bionetix's processes only.



We work for nature

21 040 rue Daoust, Ste-Anne-de-Bellevue Quebec, Canada H9X 4C 514 457 2914 • F 514 457 3589 • *www.bionetix-international.com*