

CASE HISTORY SPOTLIGHT

Cortec® Case History 317: Superior Corrosion Protection of Engines with VpCI®-126



A Brazilian automotive manufacturer was disappointed when the bags they used to package engines for shipment from Brazil to France failed to stop corrosion. The customer wanted a multi-metal protection solution involving nitrate-free bags that would be safe for users to handle.

VpCI[®]-126 bags saved the day by supplying the necessary corrosion protection, and the customer knew the best product had been selected for the job!

Read the full case history here:<u>https://</u> www.corteccasehistories.com/?s2member_file_download=ac-cess-s2member-level1/ch317.pdf

4119 White Bear Parkway, St. Paul MN 55110 USA Phone (651)429-1100, Toll free (800) 4-CORTEC Fax (651) 429-1122, Email: info@cortecvci.com www.cortecvci.com



ISO Accreditations apply to Cortec's processes only. Printed on recycled paper/100% Post Consumer

©2019, Cortec® Corporation. All Rights Reserved. Copying of these materials in any form without the written authorization of Cortec® Corporation is strictly prohibited.