


## **CASE HISTORY SPOTLIGHT**

## Case History #328: Reclaiming Motor House Castings



The customer urgently needed a number of motor house castings that had been neglected. VpCI®-422 and VpCI®-418 were used to clean off rusty surfaces, and VpCI®-377 was misted over the casting for future protection. In one week, the customer was able to reclaim all castings that would have otherwise been scrapped. The result saved time, money, and peace of mind for the customer.

Learn more about this application here: <a href="https://www.corteccasehistories.com/?s2member\_file\_download=access-s2member-level1/ch328.pdf">https://www.corteccasehistories.com/?s2member\_file\_download=access-s2member-level1/ch328.pdf</a>

4119 White Bear Parkway, St. Paul MN 55110 USA Phone (651)429-1100, Toll free (800) 4-CORTEC Fax (651) 429-1122, Email: info@cortecvci.com www.cortecvci.com

