





HIGH PERFORMANCE VpCI® PACKAGING

CASE HISTORY SPOTLIGHT

Case History #486: Preservation of Electrical Control Cabinets



More than 20 years ago, an electricity company in Northern Ireland was dealing with expensive issues and customer inconvenience due to failures in outdoor electrical control cabinets. The culprit was corrosion and proved to be most severe near the coast. In the year 2000, the company began long-term use of a VpCI® corrosion solution. The cabinets were wrapped in VpCI®-126 Blue Film during storage and transport. VpCI®-111 Emitters were placed inside operating cabinets during maintenance checks. This has turned out to be an economical and long-lasting solution that is easy to use and minimizes repair time and failure costs.

Read the full case history and see pictures here:

https://www.corteccasehistories. com/?s2member_file_download=access-s2member-level1/ch486.pdf.

4119 White Bear Parkway, St. Paul MN 55110 USA Phone (651)429-1100, Toll free (800) 4-CORTEC Fax (651) 429-1122, Email: info@cortecvci.com www.cortecvci.com

