

CASE HISTORY SPOTLIGHT

Case History 597: Cortec® Restores CorteCros® Warehouse Using MCI® Products



After 40 years in a harsh marine environment, Cortec's CorteCros® warehouse in Split, Croatia, was in serious need of exterior restoration.

The dirty walls and peeling paint were cleaned off by pressure washing with MCI®-2060 Concrete Cleaner/Degreaser. MCI®-2006 NS was used in repair mortar for damaged surfaces on the walls. MCI® Architectural Coating Gray was applied to the building wall façade, while MCI® Architectural Coating Green was used on the jamb and plinth. CorrVerter® was applied to corroded parts of the metal doors and covered with a topcoat of VpCI®-386 Green.

CorteCros® expects to get 15-20 more years of service life out of the building after the restoration.

Read the original case history at: https://www.corteccasehistories.com/?s2member_file_download=access-s2member-level1/ch597.pdf.

4119 White Bear Parkway, St. Paul MN 55110 USA
Phone (651)429-1100, Toll free (800) 4-CORTEC
Fax (651) 429-1122, Email: info@corotecvci.com
www.corotecvci.com



CORTEC
CORPORATION

Environmentally Safe VpCI®/MCI® Technologies