

SURFACE PREPARATION PRODUCTS

CASE HISTORY SPOTLIGHT

Case History #670: Protecting Heavy Equipment Fuel Tanks Near the Sea



A heavy equipment dealer was having trouble with corrosion on almost all of its units' fuel tanks stored in corrosive conditions near the sea. A Cortec® solution was proposed, and the rust was cleaned out of the tank using VpCI®-423 and MCI® Super Remover (diluted, for very severe rust). The tanks were rinsed with a dilution of VpCI®-416 and flushed with diesel fuel. VpCI®-705 Bio was added for internal protection, and tank exteriors were protected with VpCI®-386, a permanent topcoat custom-tinted to the original equipment color. The method turned out to be a much-needed solution, and the client was satisfied with the results – especially the fact that a grinding tool was no longer needed for cleaning.

To read the original case history, please visit:
https://www.corteccasehistories.com/?s2member_file_download=access-s2member-level1/ch670.pdf

4119 White Bear Parkway, St. Paul MN 55110 USA
 Phone (651)429-1100, Toll free (800) 4-CORTEC
 Fax (651) 429-1122, Email: info@cortecvci.com
www.cortecvci.com



CORTEC
 CORPORATION

Environmentally Safe VpCI®/MCI® Technologies