

CASE HISTORY SPOTLIGHT

Bionetix® Case History #21: Solving Restaurant Odor Problems and Blocked Sewerage

MUNICIPAL WASTE
TREATMENT

CASE HISTORY Restaurant Sewerage Blockage and Grease Trap Odor Control



Image courtesy of IT Tatyana Kumbarkova

DATE
December 2017

LOCATION
Ryazan, Russia

CUSTOMER
Golden Spur Restaurant

PRODUCT
BCP22™
ECO-TRAP™L

PROBLEM

Several years ago, the customer had trouble with operating the sewerage and grease trap in its restaurant. Frequent blockages and clogging of the sewerage, plus an unpleasant odor coming from the grease trap, became a headache.

APPLICATION

The solution was to add biological products ECO-TRAP™L and BCP22™ directly into the sewer pipe (via the drain holes in the sinks) and grease trap.

CONCLUSION

The customer concluded that both products were effective and wrote an official letter of recommendation encouraging their use in food production facilities.

A restaurant in Russia was having real problems with its sewerage and grease trap system. The sewerage was frequently clogged, and an unpleasant odor was coming from the grease trap. After beginning to add ECO-TRAP™L and BCP22™ to the grease trap and down the sink drain holes, the restaurant found these biological treatments to be effective and ended up writing an official letter of recommendation for their use in other food production facilities.

To read the full case history, please visit: http://www.bionetix-international.com/wp-content/uploads/Restricted_Case_Histories/ch021.pdf

ch021 12/2018

Printed on recycled paper • 100% Post Consumer

©2018, Bionetix® International. All Rights Reserved. Copying of these materials in any form without the written authorization of Bionetix® International is strictly prohibited. Your authorization applies to Bionetix's previous work.

Bionetix



We work for nature

Bionetix® International Corporation, Inc.
21 040 rue Daoust, Ste-Anne-de-Bellevue Quebec, Canada H9X 4C7
T 514 457 2914 • F 514 457 3589 • www.bionetix-international.com

