



MIGRATING CORROSION INHIBITORS
FROM GREY TO GREEN



CORTEC
CORPORATION

Environmentally Safe VpCI®/MCI® Technologies



MIGRATORY CORROSION INHIBITOR (MCI®) PRODUCTS FOR CONCRETE

CASE HISTORY SPOTLIGHT

Case History #253: Condo Balcony Repair



As part of a balcony repair project, a condominium complex in Cincinnati needed overhead patching and caulking followed by a sealer. Cortec® MCI®-2019 was chosen for the latter as a two-in-one Migrating Corrosion Inhibitor™ / water repellent that could be applied in one step. The condominium owner ultimately expressed satisfaction with the application and performance of MCI®-2019 during the project.

To read the full case history, please visit:
https://www.corteccasehistories.com/?s2member_file_download=access-s2member-level1/ch253.pdf

Keywords: balcony repair, corrosion inhibitor, water repellent, MCI-2019, Migrating Corrosion Inhibitors, Cortec, condominium repair