





HIGH PERFORMANCE VPCI® PACKAGING

Case History Spotlight #687: Transmission Preservation with CorrLam®



A logistics company in Thailand had 263 transmissions that it needed to store and preserve for five to seven years. They chose to wrap and seal each transmission in a piece of CorrLam® LD VpCl® Barrier Laminate. The product was easy to use and satisfactory to the customer. As of four years into the storage period, there were still no corrosion complaints!

To read the full case history, please visit: https://www.corteccasehistories.com/?s2mem-ber_file_download=access-s2member-level1/ch687.pdf

Keywords: transmission preservation, Cortec Case History, CorrLam, auto service parts storage, prevent corrosion on metal parts, auto industry problems, Cortec, parts preservation, auto industry, automotive parts storage

4119 White Bear Parkway, St. Paul, MN 55110 USA Phone: (651) 429-1100, Toll-free: (800) 4-CORTEC Fax: (651) 429-1122, Email: productinfo@cortecvci.com www.cortecvci.com

