

Development and Application of a New Solution for Mitigation of Carrier Pipe Corrosion Inside Cased Pipeline Crossings

LEN J. KRISSA, Enbridge Pipelines, Inc.,
Edmonton, Alberta, Canada

JERRY DEWITT, Enbridge Pipelines, Inc.,
Griffith, Indiana

TIM WHITED, MESA, Tulsa, Oklahoma

Increasing emphasis is being placed upon control of carrier pipe corrosion inside cased pipeline crossings from both an operator and regulatory perspective. Inline inspection associated with pipeline integrity management programs has identified external carrier pipe corrosion inside casings. Many factors contribute to this corrosion concern. Systems designed to proactively mitigate corrosion inside cased crossings were not readily available. The desire for a proactive carrier pipe corrosion control system led a pipeline operator and a company expert in the manufacture and application of volatile corrosion inhibitor (VCI) chemistry to consider a new corrosion mitigation solution. This effort resulted in the development of a unique product designed to fill the annular space of a casing with a gelatinous product that proactively controls carrier pipe corrosion and prevents intrusion of water, etc. into the annular space. The gel filler has been applied inside cased crossings since late 2011. Electrical resistance probes have been installed through the casing vents and submerged in the filler to the carrier pipe surface. The probes are monitored remotely with automated technology. The corrosion rate data validates the effectiveness of the VCI filler.

According to a Southwest Research Institute 2007 study,¹ cased pipe segments are generally believed to be very safe since the time-independent threats, including third-party excavation and outside force damage, are largely eliminated. However, external corrosion of carrier pipe inside casings still poses a threat to pipeline safety. Understanding the causes and characteristics of carrier pipe corrosion is an important step forward to better management of corrosion threats within cased crossings.

External corrosion on the carrier pipe is caused by a variety of factors, including:

- A high concentration of diffused oxygen with accumulated condensation at holidays (pinholes and voids) on the carrier pipe coating, which can lead to an accelerated rate of corrosion
- General atmospheric corrosion at coating holidays on the carrier pipe
- Accelerated corrosion at coating holidays in direct contact with an electrolyte such as water or other debris
- Localized corrosion due to concentration cells or the presence of bacteria, etc.
- For casings located near a compressor station, elevated temperature may accelerate an existing corrosion cell. Elevated temperatures may also cause coating damage and expose the carrier pipe surface.

A major pipeline company has an inventory of more than 2,000 cased crossings installed throughout the various regions of Canada and the United States. For many years steel casings were commonly installed over sections of pipelines to provide

DEVELOPMENT AND APPLICATION OF A NEW SOLUTION FOR MITIGATION OF CARRIER PIPE CORROSION INSIDE CASED PIPELINE CROSSINGS

mechanical protection for those constructed under roads and railways. They incorporate electrically isolating spacers and end seals that separate the carrier pipe from the casing. Over time the integrity of the end seals can degrade, allowing for the ingress of potentially corrosive groundwater. Pipe movement caused by settling and degradation of the isolating spacers may produce a potential contact of the casing to the carrier pipe, resulting in an electrical short. These factors may present an elevated risk of external corrosion on the section of piping located within the cased crossing.

Historically, casing rehabilitation programs have included projects to fill the annular space with a di-electric wax in an attempt to mitigate carrier pipe corrosion and prevent intrusion of groundwater. In-line inspection (ILI) of cased pipeline crossings has identified the existence of external corrosion anomalies on the carrier pipe within the annular space inside cased crossings. These anomalies have been identified inside casings filled with wax, as well as unfilled cased crossings. Concern for control of corrosion at areas of disbonded coating inside cased crossings was also a focus because of awareness that portions of the pipeline system were subject to disbondment of tape coating.

This data, coupled with other factors and concerns with wax-filled casings, caused the pipeline company's Integrity Management Team to begin investigating alternative solutions in 2010. The goal of this investigation was to identify solutions that would produce proactive control of carrier pipe corrosion inside cased crossings. A company skilled in the manufacture and application of volatile corrosion inhibitor (VCI) chemistry was consulted for consideration of an ideal carrier pipe corrosion mitigation solution.

Experimental Procedures

A team comprising the engineer and research and development specialists from the corrosion inhibitor company, pipeline engineers, and a pipeline integrity expert from a major corrosion service company

began work on this project in late 2010 to early 2011. The goal was to create a product that could be used to fill the annular space of a cased crossing and proactively control carrier pipe corrosion while preventing the intrusion of external water and air into the annular space. The team then initially developed a list of criteria defining the features of an ideal casing filler. The criteria for this casing filler are as follows:

- The filler should contain ample quantities of a VCI product designed to mitigate corrosion on the external surface of the carrier pipe and the internal surface of the casing.
- The filler should contain sufficient dosages of a VCI that will migrate on a molecular level under any disbonded coatings to provide corrosion protection on the carrier pipe surface.
- The VCI in the filler should also have a vapor phase component capable of mitigating corrosion within any portions of the annular space that are not completely filled.
- The VCI in the filler should be proven to diffuse through any soil debris inside the annulus and mitigate carrier pipe corrosion on surfaces in contact with the soils.
- In order to ensure a complete fill, the product should have the viscosity of water and be at ambient temperature while the casing is being filled. Once inside the casing, the product should transform into a high-viscosity gel within a short time.
- Once transformed into a gel, the viscosity should be sufficiently high to prevent the infiltration of water into the annulus and prevent loss of the filler from the annulus.
- The filler should be electrically conductive and allow flow of cathodic protection (CP) current to the carrier pipe.
- The product needed to be non-flammable.
- The product needed to be environmentally friendly, nontoxic, free of nitrites and phosphates, and made of biodegradable materials.
- Application of the filler should not require excessive carrier pipe surface preparation.

- The casing should not need to be dry before filler application. The filler should have the ability to combine with nominal quantities of annular space water during installation. The additional water should not reduce the effectiveness of the filler's ability to mitigate corrosion of the annular space metals.
- The product should produce economical corrosion protection and minimal shipping costs.

This list of product specifications was then provided to the research and development group for the VCI company. After an initial review, a determination was made that this product could be developed with a unique combination of recognized chemistries and technical knowledge. The pipeline team then requested that the filler product be developed. By mid-2011, product development of the gel filler was progressing on schedule. The chemists at the VCI company were on track to provide a VCI gel filler product that met all of the criteria listed above. The pipeline team then designed and engineered a pilot project to test application of the filler and begin monitoring its effectiveness for control of corrosion.

The goal was to create a product that could be used to fill the annular space of a cased crossing and proactively control carrier pipe corrosion while preventing the intrusion of external water and air into the annular space.

VCI Basics for Casings

The annular space of a cased pipeline crossing is an ideal environment for the application of VCI technologies and systems.² With the development of the VCI filler gel, even greater flexibility is available for casings that may not be totally sealed.

FIGURE 1 Custom ER probe for casings.

It was important to utilize VCIs that provide corrosion control in all three environments that might potentially exist inside a cased crossing. An amine carboxylate-based VCI was selected to meet the following multiphase criteria for corrosion protection.

1. The liquid/solids phase where the metal surfaces are covered with water or soils that have migrated inside the casing or were left inside the casing during the original installation
2. The region along the interface of vapor and liquid/solids where accelerated corrosion may normally exist
3. The vapor space exposed to atmospheric corrosion conditions

The amine carboxylate-based VCI product adsorbs onto the metal surface and forms a protective mono-molecular layer on that surface within all three phases described above. This molecular layer inhibits the electrochemical reaction on the metal surface. Mitigation of corrosion with VCI chemistry is mature and well proven. VCI products have been in existence for over 30 years and there are multitudes of successful applications within numerous environments similar to the annular space of a casing.

An early documented example of VCI application for cased crossings is contained in the NACE article published in 2001 entitled "Use of Corrosion Inhibitors on the Alaska Pipeline."³ This article describes the successful application of VCIs to mitigate

corrosion inside numerous cased sections along this pipeline.

The new gel filler product is designed to totally fill the annular space of cased pipeline crossings with a water viscosity VCI product that transforms into a gel within a short time. This product is produced in two parts, with Part A being a high dosage of a specially designed liquid VCI concentrate that is mixed with water in the field. Part B is a unique superabsorbent polymer powder that is added to the liquid stream flowing to the casing, transforming the water viscosity liquid into a high-viscosity gel. These are nonhazardous, environmentally friendly products.

Corrosion Rate Monitoring Inside the Annular Space

The pipeline team decided it would be important to evaluate the effectiveness of the gel filler and its ability to maintain a noncorrosive environment over long periods of time. Team members were familiar with electrical resistance (ER) corrosion rate probe technology and decided to employ this equipment inside the casing annulus.

ER probes are commonly used on a daily basis to evaluate the corrosiveness of many types of environments inside flowing pipelines and other structures. ER probes can be installed as part of a casing integrity program before inhibitor is applied in order to identify casings with corrosive environments. They are also very useful after a VCI

is applied to evaluate the inhibitor effectiveness over the long term.

An ER probe had already been custom developed by a leading U.S. company for application inside casings. The probe is designed to be lowered down through a casing vent to the carrier pipe surface. It has a shield that prevents contact of the probe sensing element with the carrier pipe (Figure 1).

The pipeline team decided it would be important to evaluate the effectiveness of the gel filler and its ability to maintain a noncorrosive environment over long periods of time.

Multi-function Corrosion Control Monitoring System

A new and unique automated monitoring system was custom designed for use on the pilot project and also future casing applications. (Refer to CORROSION 2013 paper no. 2741,⁴ "Corrosion Rate Monitoring in Pipeline Casings," for additional information.) The system is multi-purpose and capable of monitoring CP pipe-to-soil (P/S) potentials on the pipeline 1 ft (0.3 m) from the casing, the casing potential, and corrosion rates from the ER probe installed inside the casing annulus. The system incorporates remote monitoring technology designed to capture P/S variances in real time with immediate notification transmission of readings outside of acceptable, pre-set parameters. This method of benchmarking and verification of CP and corrosion rate inhibitor performance provides a comprehensive, proactive data set through the transmission of actionable alarm data and increased frequency of logged data accessibility. The system produces a permanent, ongoing verification of VCI and CP system effectiveness as external influences vary.

The monitoring systems are equipped with the capacity to measure CP applied and polarized P/S "off" potentials and if

FIGURE 2 Remote monitoring system schematic.

applicable, induced alternating current potential and corrosion current by utilizing a dual-coupon test station design. Values are measured at predetermined time intervals and stored SD memory cards located on board the device. The monitoring systems are equipped with either satellite or cellular communication capability and readings are transmitted to the Web-based interface at a user-defined time interval. Interrogation, monitoring, reconfiguration, or system troubleshooting can also be accomplished through an Internet connection. Figure 2 shows the schematic.

Initial Casing Field Study

The pipeline company performed integrated data analysis on its Chicago Region

TABLE 1. REPAIR PRIORITY MATRIX


ILI Data Results	CP Survey Results	Priority	Proposed Action
Ext. ML Indicated	Metallic short		End-seal refurbishment w/ VCI gel injection and RMU installation ^(A)
Ext. ML Indicated	Electrolytic coupling		End-seal refurbishment w/ VCI gel injection and RMU installation ^(A)
Ext. ML Indicated	Clear (no short)		Monitor through ILI for indications of ongoing corrosion (growth), and CP for changing status of isolation
No Ext. ML	Metallic short		
No Ext. ML	Electrolytic coupling		
No Ext. ML	Clear (no short)		Wax-filled casings continue to be monitored for ongoing external corrosion
Wax-filled casing (any ILI condition)	Wax filled casing (any CP condition)		
^(A) Priority for remediation or ultimate casing removal and pipeline repair is established by severity of corrosion damage.			

FIGURE 3 Graphic depiction of casing VCI gel filler system.

pipeline system. Data from inline inspection (ILI) and CP surveillance were correlated and utilized to identify and improve prioritization of vulnerable cased crossing locations. This approach enabled more comprehensive monitoring and remediation programs to be established.

CP survey information was evaluated and locations were prioritized based upon electrical isolation status and level of protection. ILI data were prioritized accordingly on locations of high corrosion density that were approaching repair criteria. Priority for repair is summarized by the matrix presented in Table 1.

The results from the Chicago Region's analysis were leveraged and applied for long-term planning of repair on the entire system. The short-term program objectives (2011-2012) were to:

- Develop and refine conceptual end-seal refurbishment and VCI filler delivery processes at four pilot locations (2011 Q4).
- Demonstrate and prove feasibility of the

process at six to 10 locations within the Chicago Region and establish a system-wide prioritized list of locations for rehabilitation (2012 Q1-4).

The long-term program objectives (2013 to 2018+) were to:

- Reduce or eliminate extremely costly reactionary integrity or regulatory-driven repairs on pipelines at cased crossings. These repairs had historically cost \$1.5 to \$3.0+ million.
- Mitigate and monitor corrosion activity at all prioritized cased crossing locations.

2011 Casing Remediation Project

A comprehensive pilot project was initiated in late 2011 for cased crossing corrosion management at four locations. ILI data had demonstrated limited success with conventional di-electric wax fill and the operator suspected the wax fill may have sometimes compounded the problem due to incomplete fill of the void space, the non-

compatibility of the wax with water in the casing, and a lack of corrosion control under disbonded coating. Therefore, the pilot program comprised the following components:

- Modifications to vents and improved end-seal refurbishment process/materials as needed
- Sealing of the annular space inside each casing with the VCI gel filler
- Installation of automated monitoring systems designed to measure the real-time rate of corrosion inside the annulus and provide measurement of CP data

Application of VCI Gel Filler

After inspection/repair of end seals and vents, the VCI gel filler was applied into the casing annulus. Installation was accomplished with a unique set of equipment that was custom constructed for application of the VCI gel filler product. The equipment package was designed by the engineering department of the VCI manufacturer and a

major corrosion control service company already experienced with installation of VCI systems in other applications.

Once the installation and support equipment is staged near a casing, the necessary connections are made to the casing vents. Next the VCI concentrate Part A is mixed with water. The ambient temperature liquid mixture is then pumped into a hose connected to a casing vent. The Part B superabsorbent powder is added into the liquid discharge stream as it flows to the casing. After the casing is filled, the powder absorbs the liquid over a short time period and converts it into a gel. The gel surrounds the carrier pipe with a high dosage of VCI that has been proven to provide effective multi-phase inhibition of corrosion for many years. An incomplete fill of the casing due to air pockets, bends, etc. is not a concern because the inhibitor has a vapor phase component that will also provide corrosion control on the carrier pipe surface within any void space. See Figure 3 for a graphic depiction of the process.

Results

At this time seven cased crossings are monitored. The automated corrosion control monitoring systems have been collecting ER probe and CP potential data every three days for 1 to 1.5 years. All data is reported to a Web site via the remote communication capability of the systems. The corrosion rate at each ER probe is less than 1 mpy. The CP potentials do not indicate electrical shorts. Additional cased crossings will be addressed in 2013. Future ILI analysis of the carrier pipe inside the cased crossings will produce additional evaluation of corrosion control systems effectiveness.

Conclusions

ILI data make it readily apparent that corrosion does sometimes occur on the carrier pipe inside of wax filled and unfilled cased pipeline crossings. When integrity programs discover carrier pipe corrosion that is coupled with disbonded tape coating concerns inside the annular space, it becomes important to proactively mitigate this corrosion. The Pipe-

line Integrity Team has developed a well-engineered program to mitigate the corrosion through a multi-step process described in this article. The development of the amine carboxylate-based VCI gel filler designed to satisfy a number of stringent criteria is an integral component of the casing integrity program. The automated multi-function monitoring system developed for cased crossing applications keeps a close watch on the integrity of the corrosion control systems at each cased crossing. As a result of the collaborative processes described in this paper, a number of innovations have resulted to provide a solid foundation for methodically addressing carrier pipe integrity inside cased crossings.

The Pipeline Integrity Team has developed a well-engineered program to mitigate the corrosion through a multi-step process.

Acknowledgments

The authors give special thanks to the Enbridge Pipeline Integrity team, and Charlie Hall and Mark Cadle of MESA.

References

1. Southwest Research Institute, "Statistical Analysis of External Corrosion Anomaly Data of Cased Pipe Segments," INGAA Foundation, Report No. F-2007-10, December 2007.
2. Tim Whited, "Corrosion Inhibitor Solutions for Proactive Control of Corrosion Inside Cased Pipeline Crossings," supplement to *MP* 51, 6 (2012).
3. Ernest W. Kletchka, "Use of Corrosion Inhibitors on the Alaska Pipeline," supplement to *MP* 40, 1 (2001).
4. Jamey Hilleary, et al., "Corrosion Rate Monitoring in Pipeline Casings," *CORROSION* 2013, paper no. 2741 (Houston, TX: NACE International, 2013).

This article is based on CORROSION 2014 paper no. 4167, presented in San Antonio, Texas.

LEN J. KRISSA is an engineering specialist at Enbridge Pipelines, Inc., 10201 Jasper Ave., Edmonton, AB T5J 3N7, Canada. He has gained extensive international experience on pipeline evaluation projects, applying modern survey techniques to CP and coating field evaluations. He has been associated with various pipeline management programs and assisted in the design and development of new survey equipment and procedures. He is currently a pipeline integrity engineering specialist at Enbridge, where his role involves the integration of ILI and metal loss data with CP survey results along with managing alternating current and casing corrosion prevention. Krissa is a professional engineer, registered through Apega, and has been involved with the pipeline corrosion industry for more than 20 years. He is a NACE-certified Cathodic Protection Specialist (CP4) in conjunction with having NACE Level 2 Coating Inspector certification. He has been a member of NACE since 2000.

JERRY DEWITT is the senior cathodic protection specialist at Enbridge Energy, 222 U.S. Hwy. 41, Schererville, IN 46375. He is involved in the design, operation, and maintenance of CP systems for pipelines and aboveground storage tanks. He is a NACE-certified Cathodic Protection Specialist (CP-4), Level 3 Coating Inspector, and Internal Corrosion Technologist. He has been a member of NACE for 28 years.

TIM WHITED is the corrosion solutions director of business development at MESA, 4445 S. 74th E. Ave., Tulsa, OK 74145, e-mail: tim.whited@mesaproducts.com. He has 35 years of experience in the field of corrosion control and extensive experience with both CP and VCIs. He has a B.S. degree in mathematics and has been a NACE-certified Cathodic Protection Specialist (#3245) since 1992. He has co-authored six NACE annual conference technical papers and has been a member of NACE for 33 years. **MP**